
## CPA 25 \* 25 packing specification



1. Put Patch 50pcs in each tray (800001000205).



2. Stack 4 trays.



3. Put foam which has 1cm thickness on the top of tray & fix it by package machine.

UNLESS OTHER SPECIFIED								
X= X.X=	X.XX=	INPAQ TECHNOLOGY CO.,LTD						
ANGLES=± HOLEDIA=								
SCALE :	UNIT :	THIS DRAWING	NGS AND SPECIFICATIONS ARE THE PROPERTY OF INPAQ					
DRAWN BY:蕭富美	CHECKED BY:曾源標	TECHNOLOGY CO.,LTD.AND SHALL NOT BE REPRODUCED OR USED AS THE BASIS FOR THE MANUFACTURE OR SALE OF APPARATUS OR						
DESIGNED BY:馬敏勝	APPROVED BY:曾泓瑋	DEVICES WITHOUT PERMISSION						
TITLE : CPA 25 * 25 packing specification		DOCUMENT	PKG00000	SPEC REV.				
		NO.		A2				
			PAGE	1 OF	2			



4. Sealed by vacuum packaging & labeling as drawing.

5. Put partition (80000010306) into the bottom of inside carton (8000012023025). Put 200pcs products into the inside carton & label each carton.

6. Put 4 inner cartons in 1 shipping carton (800001805203). Each shipping carton should contain 800pcs.

UNLESS OTHER SPECIFIED									
X= X.X=	X.XX=	INPAQ TECHNOLOGY CO.,LTD							
ANGLES=± HOLEDIA=									
SCALE :	UNIT :	THIS DRAWING	THIS DRAWINGS AND SPECIFICATIONS ARE THE PROPERTY OF INPAQ						
DRAWN BY:蕭富美	CHECKED BY:曾源標	TECHNOLOGY CO., LTD. AND SHALL NOT BE REPRODUCED OR USED AS THE BASIS FOR THE MANUFACTURE OR SALE OF APPARATUS OR							
DESIGNED BY:馬敏勝	APPROVED BY:曾泓瑋	DEVICES WITHOUT PERMISSION							
TITLE : CPA 25 * 25 packing specification		DOCUMENT	PKG00000017			SPEC REV.			
		NO.				A2			
			PAGE	2	OF	2			